

## LEAD INSPECTOR

1. Audit out-going shipments including shipment appearance.
2. Make other shifts aware of quality concerns on production jobs.
3. Perform quality checks at specified intervals.
4. Check paperwork from other shifts to ensure that it is completely and correctly filled out.

UNCONTROLLED